

Oil Field Environmental Incident Summary

Incident: 20140129170716 **Date/Time of Notice:** 01/29/2014 16:46

Responsible Party: Zavanna, LLC

Well Operator: ZAVANNA, LLC

Well Name: HARSTAD 1-15H

Field Name: STOCKYARD CREEK

Well File #: 16481

Date Incident: 1/29/2014 **Time Incident:** 14:30

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 99

Sec: 15

Qtr:

Location Description:

Submitted By: Drew Tooley

Received By:

Contact Person: Drew Tooley
1200 17TH STREET STE 1100
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 miles

Distance Nearest Water Well: 20 feet

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	60	barrels	10	barrels	56	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/7/2014

Clean Up Concluded: 3/3/2014

Risk Evaluation:

None

Areal Extent:

50 yds off location

Potential Environmental Impacts:

Soil contamination

Action Taken or Planned:

Well was shut in and Black Duck Services was contacted to provide cleanup services. Gaskets will be tested and replaced in the future to prevent this from happening again.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 1/30/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, was not contained on location. Followup is necessary. Communication with company rep indicates that the 20-foot distance to well is not correct. It refers to the distance from the pad edge to a surface water body. This information is pending confirmation from the field inspector who will be visiting the site in the near future.

Date: 1/31/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 14:51 1/31/14.

Cleanup currently under way with a fair amount of work left. A majority of the oil-impacted material has been removed, with only small areas left with visible oil staining. It was recommended to the contractor that absorbent booms be staked down in the drainage to prevent nonpoint source impacts.

More followup is required to ensure complete remediation.

Date: 2/6/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/6/14 - 17:30 on location. Spray from treater upset went off location to the east. Vegetation and snow pack from off-site impact has been removed. No further inspection required.